

Technical Service Bulletin

**MODEL(S)
AFFECTED:**

Tennant 5680, 5700, 7200 (disk scrub brush models only, ~~with or without the FaST option~~)

SUBJECT:

Uneven solution distribution to the scrub brushes, resulting in reduced scrubbing performance and the motor for the brush receiving the smaller amount of solution drawing more amperage.

PURPOSE:

Drill a hole into the top of both solution hoses attached to the t-fitting.

NOTES:

Drill a 1/16" hole into the top of both solution hoses attached to the t-fitting. Refer to drawing below for locations of holes.

Questions, contact the Tennant Customer Service Department at (800) 553-8033 or (763) 513-2850.

