

Technical Service Bulletin

MODEL(S) AFFECTED:	T3 Scrubber (NA and International models only, excludes Europe) Model serial number range: ...10202477 (Nov 2004) →...10278353 (March 2006)
SUBJECT:	Brush driver mounting screw backing out, resulting in brush driver and motor damage.
PURPOSE:	To prevent potential damage, add thread locking compound as described below.
NOTES:	Inspect machines during routine maintenance visits and unrelated service calls. For questions, contact the Tennant Customer Service Department at (800) 553-8033 or (763) 513-2850.

