

No. 149

Release Date:
06/11/2008



Technical Service Bulletin

MODEL(S) AFFECTED: Tennant S30, S30 XP, S30 X4 (Machines serial numbers 001000-001089)

SUBJECT: Side shroud rattling due to vibration when machine is operated

PURPOSE: Eliminate side shroud rattling

NOTES: Order Bumper Kit, Door, Side [S30]-9004901. The IB for this kit is 9004902.
Questions, contact Tennant Customer Service Department at (800) 553-8033 or (763) 513-2850.
Warranty Information: Standard Terms Apply.

