

Technical Service Bulletin

MODEL(S) AFFECTED: **Tennant S30, S30 XP, S30 X4 (serial numbers 001000-001429)**

SUBJECT: Machine excessively dusting due to filter shaker light not illuminating (alerting operator) when the filter needs to be shaken.

PURPOSE: Move the hose fitting from the filter housing to the duct above the vacuum fan.

NOTES: Order kit #9005920 – FITTING KIT [SHAKE-BACK LIGHT S30]. The IB for kit 9005920 is IB 9005919. Refer to the IB for instructions how to install the vacuum fitting kit.
Questions, contact the Tennant Customer Service Department at (800) 553-8033 or (763) 513-2850.
Warranty Information: Standard Terms Apply.

How dust filter housing should appear after installation of kit #9005920.

