

Technical Service Bulletin

MODEL(S) AFFECTED: **Speed Scrub 500 Scrubbers equipped with Smart-Fill™ ABW system**
Models manufactured before December, 2018

SUBJECT: The ABW tank float switch may give a false indication of an empty tank.
When the scrub head is in raised positioned, a magnetic field between the brush motor and float switch may cause the float switch to activate inadvertently.

PURPOSE: To prevent the above condition, order float switch shield kit (p/n 9018447).

NOTES: **Warranty Information:** Standard warranty terms apply.

False indication of an empty ABW tank.



Float Switch Shield Kit (p/n 9018447)

The float switch shield kit attaches to the float switch as shown below.

