

Technical Service Bulletin

MODEL(S) AFFECTED: M20 (Serial Numbers 005700-014639)/T20 (Serial Numbers 005000-013710)/
M30 (Serial Numbers 004000-010345) Equipped With Mitsubishi Gas/LP Engines

SUBJECT: Hot exhaust pipe can potentially touch lower radiator hose, causing heat damage to hose and possibly a coolant leak.

PURPOSE: Install clamp to secure lower radiator hose to engine mounting bracket and away from the exhaust pipe. Replace lower radiator hose if damaged.

NOTES: Refer to IB 9010906 for instructions to access/replace the lower radiator hose/hardware. Parts required to secure lower radiator hose away from exhaust system listed/shown in diagram below. Questions, contact the Tennant Customer Service Department at (800) 553-8033/ TNV contact 0031 (0) 413241242.

Warranty Information: Standard warranty terms apply.

