



INSTRUCTION BULLETIN

No. 340046
Machine: 355
Published: 3-97/00
System: HYDRAULICS

NOTE: DO NOT DISCARD the Parts List from the Instruction Bulletin. Place the Parts List in the appropriate place in your machine manual for future reference. Retaining the Parts List will make it easier to reorder individual parts and will save you the cost of ordering an entire kit.

NOTE: Numbers in parenthesis () are reference numbers for parts listed in Bill of Materials.

Motor Replacement Kit Number 378720

SYNOPSIS:

This kit contains the new motor 361025, repair information bulletin, repair parts list, and parts breakdown for hydraulic motor part # 361025.

When repairing this motor please follow step-by-step instructions in the repair information bulletin (Part # 79729 / Eaton # 7-124).

REPAIR PARTS LIST FOR MOTOR PART # 361025

Ref.	TENNANT Part No.	Description	Qty.
1	21951	Shaft, bearing kit	1
2	51417	Plate	1
3	02603	Drive	1
4	21952	Bearing housing	1
5	02645	Geroler	1
6	02646	Valve plate	1
7	57370	Valve drive	1
8	02647	Valve	1
9	57373	Balance ring	1
10	57374	Pin	2
11	57375	Spring	2
12	74119	Valve housing	1
13	74098	#4 plug	1
14	74120	Bolt	4
15	38315	Key	1
16	38490	Nut	1
17	21953	Seal kit	1
18	79729	Repair information bulletin	1

TENNANT COMPANY
P. O. Box 1452
Minneapolis, MN 55440-1452




FIG. 1 - MOTOR PARTS BREAKDOWN (PART # 361025)