



# INSTRUCTION BULLETIN

No. 340747

Machine: 6600/6650, 7400,  
8200/8210, 800/810, 8410

Published: 06-2004

Rev. 00

**NOTE: DO NOT DISCARD the Parts List from the Instruction Bulletin. Place the Parts List in the appropriate place in the machine manual for future reference. Retaining the Parts List will make it easier to reorder individual parts and will save the cost of ordering an entire kit.**

*NOTE: Numbers in parenthesis ( ) are reference numbers for parts listed in Bill of Materials.*

Installation instructions for **kit number 9000963**

## SYNOPSIS / PROBLEM:

This kit contains labels needed to replace missing and/or badly damaged labels on 6600/6650, 7400, 8200/8210, 800/810, and 8410 model sweepers.  
Please follow step-by-step instructions.

## SPECIAL TOOLS / CONSIDERATIONS: NONE

(Estimated time to complete: 1/2 hour)

## PREPARATION:

1. Park the machine on a clean level surface.


**FOR SAFETY: Before leaving or servicing machine, stop on level surface, turn off machine, and remove key.**

2. If necessary, allow vehicle to cool before installing labels.

**FOR SAFETY: Components will be hot if machine has been in operation. Do not touch hot components. Allow machine to cool down before performing maintenance.**

## INSTALLATION: 6600/6650 machine

1. Use a clean cloth with isopropyl alcohol (or a similar cleaning solution) to clean any residue, from the previous label or dirt from the machine. The new label may not adhere to the machine if there is remaining dirt or residue from the previous label. Refer to Fig. 1 for label location.



**FIG. 1**

2. Allow cleaned area to dry.
3. Carefully affix the new label to the machine. Do not allow label to wrinkle. Be sure to rub air pockets out from under the label.
4. Store extra labels in a dry and clean area. Do not discard extra labels since they can be used later.

### INSTALLATION: 7400 machine

1. Use a clean cloth with isopropyl alcohol (or a similar cleaning solution) to clean any residue from the previous label or dirt from the machine. The new label may not adhere to the machine if there is remaining dirt or residue from the previous label. Refer to Fig. 2 for label location.



FIG. 2

2. Allow cleaned area to dry.
3. Carefully affix the new label to the machine. Do not allow label to wrinkle. Be sure to rub air pockets out from under the label.
4. Store extra labels in a dry and clean area. Do not discard extra labels since they can be used later.

### INSTALLATION: 8200/8210 machine

1. Use a clean cloth with isopropyl alcohol (or a similar cleaning solution) to clean any residue from the previous labels or dirt from the machine. The new labels may not adhere to the machine if there is remaining dirt or residue from the previous label. Refer to Fig. 3 for location of label.



FIG. 3

2. Allow cleaned area to dry.
3. Carefully affix the new labels to the machine. Do not allow labels to wrinkle. Be sure to rub air pockets out from under the labels.

### INSTALLATION: 800/810 machine

1. Open the door to the engine compartment.
2. Use a clean cloth with isopropyl alcohol (or a similar cleaning solution) to clean any residue from the previous label or dirt from the machine. The new label may not adhere to the machine if there is remaining dirt or residue from the previous label. Refer to Fig. 4 for label location.




FIG. 4

3. Allow cleaned area to dry.
4. Carefully affix the new label to the machine. Do not allow label to wrinkle. Be sure to rub air pockets out from under the label.
5. Store extra labels in a dry and clean area. Do not discard extra labels since they can be used later.

## INSTALLATION: 8410 machine

1. Open the door to the engine compartment.
2. Use a clean cloth with isopropyl alcohol (or a similar cleaning solution) to clean any residue from the previous labels or dirt from the machine. The new labels may not adhere to the machine if there is remaining dirt or residue from the previous labels. Refer to Fig. 5 and Fig. 6 for label locations.




FIG. 5



FIG. 6

3. Allow cleaned areas to dry.
4. Carefully affix the new labels to the machine. Do not allow label to wrinkle. Be sure to rub air pockets out from under the labels.

---

### Bill of Materials for Decal Kit, Hi Temp, CI 9000963

	Ref.	Tennant Part No.	Description	Qty.
▽		9000963	Decal Kit, Hi Temp ,CI	1
▲	1	1017141	Label Set, Hi Temp	2
▲	2	1016998	Label, Hot Surface, Hi Temp	2

TENNANT COMPANY  
P. O. Box 1452  
Minneapolis, MN 55440-1452