

# Technical Service Bulletin

**MODEL(S)  
AFFECTED:**
**Tennant 1510 Automatic Carpet Extractor**

(Models manufactured before Serial Number 90050-10311505 DC1206)

**SUBJECT:**


Reports have been received that the wire leading to the vacuum motor circuit breakers may be underrated and may result in frequent tripping and/or minor wire damage.

**PURPOSE:**

To prevent frequent circuit breaker tripping and potential wire damage, install Wire Harness Kit (p/n 9003284) shown below. The kit is designed to reduce the current load on the single wire leading to the vacuum motor circuit breakers.

**NOTES:**

To order kit, contact the Tennant Customer Service Department at (800) 553-8033 or (763) 513-2850. The kit is covered under warranty. Follow the standard warranty claim process.

**Current Wiring Configuration**

**Wire Configuration with Wire Harness Kit Installed**
