Release Date: 12/02/2009



Technical Service Bulletin

MODEL(S) AFFECTED: Tennant S20 Electric Machines (serial numbers 000000-001070)

SUBJECT: Clogged filter light not operating (to alert operator that the filter is clogged and needs to be

shaken) due to the vacuum hoses from the cyclone cover and filter cover connected to the wrong

ports on the pressure switch.

PURPOSE: Inspect hoses and move incorrectly installed hoses to the correct ports on the pressure switch.

NOTES: The hose from the filter cover should be connected to the LOW port on the pressure switch. The hose from the cyclone cover should be connected to the HIGH port on the pressure switch. Refer to photos below.

Test the system: With the key on, remove the hose from the filter cover and apply a slight vacuum. The light will illuminate and the alarm will sound if the hoses are connected to the correct locations on the pressure switch.

Questions, contact the Tennant Customer Service Department at (800) 553-8033 or (763) 513-2850.

Warranty Information: Standard Terms Apply.







