



Technical Service Bulletin

| PRODUCT(S) AFFECTED: | FaST 365 Floor Cleaning Concentrate (p/n's 1010601, 1010602, 102889, 1002887) | |
|-------------------------|--|--|
| SUBJECT: | Early production batches of FaST 365 Floor Cleaning Concentrate (see Batch Numbers below) may become thickened due to aging. | |
| | Affected concentrate may clog the machine's FaST system. | |
| | A new formula began shipping in June 2004 that eliminated the ingredient which caused the shelf life problem. | |
| | New formula shelf life is 2 years when stored above freezing temperatures. | |
| PURPOSE: | If the Batch Numbers below exist in your inventory, the product should be returned. Tennant will replace the product at no cost. The Batch Number dates fall between June 13, 2003 and May 26, 2004. | |
| NOTES: | Please contact the Customer Service Department at (800) 553-8033 or (763) 513-2850 to arrange for the exchange. | |

| Batch Numb | ers | | |
|--|---|-------------------|--|
| 06-134C 06-134C-2 06-184C 06-234C 07-014C 07-024C 07-164C 07-174C 07-314C 08-014C 08-064C 08-144C 08-194C 09-084C 09-224C 09-224C 09-234C 10-014C 10-164C 11-064C | 11-174C 11-254C 12-044C 12-174C 12-264C 12-274C 01-055C 01-145C 01-285C 01-305C 02-055C 02-195C 03-035C 03-155C 03-265C 04-135C 04-195C 05-065C 05-185C | Batch Number — | Designation of the state of the |