


**TECHNICAL SERVICE BULLETIN, 980550-003****DATE: 1/98****TITLE:****HOSE ADAPTOR, VACUUM INTAKE****APPLICABLE MACHINES:****550****SYNOPSIS:**

The hose adaptor located in the tractor frame weldment can be ordered separately for replacement.

The hose adaptor located in the tractor frame weldment, where the vacuum intake from the tank attaches, can be ordered separately for replacement.

The hose adaptor is Tennant Company part number 53355-1.

**TRACTOR FRAME**

00314