

Technical Service Bulletin

MODEL(S) AFFECTED: Tennant 7400/7400D, 8400/8400D, 8410/8410D equipped with ES pump option with back flush feature

SUBJECT: The back flush feature on the ES pump has been discontinued from production.

PURPOSE: Replace the ES pump (with back flush option) with a new ES pump (without back flush option).

NOTES: 7400/8410 machines equipped with the new ES pump began shipping at the end of November 2005. Order Pump Kit, ES, F/20891, Replmt [7400/8410]-377422 if existing ES pump has failed. The IB for the kit is 340785. Refer to the ES Pump Assembly Without Back Flush-377422 drawing below for parts included in this kit.

Questions, contact the Tennant Customer Service Department at (800) 553-8033 or (763) 513-2850.

